

From: [Scott Miller](#)
To: [Hutton Richard H](#); [John Mousa](#)
Subject: Fw: Floridan IRM and other groundwater well issues
Date: Wednesday, May 30, 2012 5:31:23 PM

Scott Miller
Remedial Project Manager
Superfund Division
Superfund Remedial Branch
Section C
U.S. EPA Region 4
61 Forsyth Street, SW
Atlanta, GA 30303
Phone (404) 562-9120
Fax (404) 562-8896

-----Forwarded by Scott Miller/R4/USEPA/US on 05/30/2012 05:30PM -----

To: "Erickson Jim" <Jim.Erickson@tetrattech.com>, "Brouman Mitch (Pittsburgh) NA" <Mitch.Brouman@hanson.biz>
From: Scott Miller/R4/USEPA/US
Date: 05/30/2012 05:19PM
Subject: Floridan IRM and other groundwater well issues

Gentlemen,

Greetings, wanted to follow up with you on getting a finalized IRM report with data from the increased frequency of sampling there and what are proposed as next steps. In looking at data that was presented to date, it appears that the "drag down theory" does not fully explain the contamination found at FW-6 and FW-21B.

Are there plans to go ahead and add a dedicated Floridan recovery well at that location?

In addition, we'd like to begin a dialogue as it relates to offsite drinking water wells and irrigation wells that still exist nearby. We would look for additional sampling and possibly well abandonment where property owners would allow such to take place.

Thanks,

Scott Miller
Remedial Project Manager
Superfund Division
Superfund Remedial Branch
Section C
U.S. EPA Region 4
61 Forsyth Street, SW
Atlanta, GA 30303
Phone (404) 562-9120
Fax (404) 562-8896